## WATER QUALITY MEMORANDUM

Utah Coal Regulatory Program

October 13, 2008

TO:	Internal File		
THRU:	Daron Haddock, Permit Supervisor		
FROM: SUBJECT:	April Abate, Environmental Scientist/Hydrologist  2008 First Quarter Water Monitoring, Canyon Fuel Company, Banning Siding  Loadout, C/007/0034-WQ08-1, Task #2718		
The Ba	anning Siding Loadout has been in temporary cessation since 2000.		
Pertinent water monitoring requirement information is in the MRP in Sections 731.210, and 731.220 and the UPDES General Coal Mining Permit No. UTG040011 for Canyon fuel Company, LLC - Banning Loadout Facility			
1. Was data	submitted for all of the MRP required sites? YES NO		
<u>Springs</u> – <i>Loado</i>	The Permittee is not required to monitor any springs at the Banning Siding ut.		
<u>Streams</u> – <i>Loados</i>	The Permittee is not required to monitor any streams at the Banning Siding ut.		
Wells–  Dump	During temporary cessation, the Permittee is required to sample the "Truck Sump during the "late fall."		

## **UPDES**-

There are two active UPDES sites at the Banning Siding Loadout. They are both under the permit #UTG040011, and are the primary and emergency spillways for the sedimentation pond. The Permittee is required to monitor each UPDES site monthly.

The Truck Dump Sump will be monitored in the fourth quarter.

The Permittee monitored and reported the essential data for all UPDES data points as required during this quarter. None of the UPDES sites recorded any flow during the period.			
2. Were all required parameters reported for each site?	YES	NO 🖂	
Not applicable, as no flow was reported.			
3. Were any irregularities found in the data?	YES 🗌	NO 🖂	
Not applicable.			
4. On what date does the MRP require a five-year re-sampling of baseline water data.			
The MRP does not contain a commitment for re-sampling of baseline water data.			
5. Based on your review, what further actions, if any, do you recommend?			
The Division copy of the UPDES permit on file was expired. On 10/8/08, the Division requested from the mine operator an updated copy of the UPDES permit for the file. On 10/13/08, a copy of the current UPDES permit was received from the Department of Water Quality and placed in the UPDES permit binder. No further actions are required at this time.			

O:\007034.BAN\WATER QUALITY\BANNINGWQ\_08-1.DOC